



No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
1	Dust cap	1
2	Roundwire snap rings for shaft 18.5x2	1
3	Steel ball holder	1
4	Conical spring	1
5	Cylinder case	1
6	Soket head cap screw M5x22	4
7	Spring washer 5	4
8	Flat washer 5	4
9	Gasket ring	1
10	Oil seal 30x42x7	1
11	Washer 37x47x1	1
12	Circlip 33	1
13	Bearing 6906RS-GRSC	1
14	Distance ring	1
15	Circlip for hole 50	1
16	Steel ball 7.14	5
17	Drill sleeve	1
18	O ring 19.8x2.1	2
19	O ring 11x2	2
20	Impact bar	1
21	Steel ball 5.5	3
22	Cylinder	1
23	Flat key 3x3x18	2
24	Circlip 33	1
25	Washer 30x37x2	1
26	Spring 3.5x31x57	1
27	Bevel gear wheel	1
28	Circlip 33	2
29	Striker	1
30	O ring 18x3.1	2
31	Piston pin	1
32	Piston	1
33	Connecting rod	1
34	Needle roller bearing HK0810	1
35	Oil bearing	1
36	Mode selector switch (drill stop)	1
42	+ Pan head screw M4x12	2
43	+ Pan head screw M4x8	1
44	Oil filler cap	1
45	O ring 37.5x1.8	1
46	Crank shaft	1
47	Gearbox	1
48	Bearing 6003Z	1
49	Circlip for hole 35	1
50	Circlip for shaft 17	1
51	Spring Ø1.2x7.8x32	1
52	Flat key 4.8x22	1
53	Pin 8x20	1
54	First gear	1
55	Supporting sleeve	1
56	Needle roller bearing HK1208	1
57	Gasket ring	1
58	Steel ball 4	1
59	O ring 11x2.5	1

No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
60	Rotating shaft	1
61	Mode selector switch (chisel stop)	1
62	Flat washer 5	1
63	Spring washer 5	1
64	+ Pan head screw M5x14	1
65	Bevel pinion	1
66	Bearing 6002Z	1
67	Washer Ø20xØ14x0.5	1
68	Flat key 3x10	1
69	Safety clutch	1
70	Roundwire snap rings for shaft 12.5x1	1
71	Steel ball 5.5	8
72	Second gear	1
73	Gear pressing plate	1
74	Bearing 627Z	1
75	Gearbox cover	1
76	Ball bearing 6001RS	1
77	Rotor	1
78	Wind deflector	1
79	Stator	1
80	+ Pan head tapping screw ST4.8x50	2
81	Ball bearing 608Z	1
82	Motor casing	1
83	Brush holder	2
84	Brush	2
85	Brush holder cover	2
86	Air filter net	1
87	Pressing plate	1
88	+ Pan head tapping screw ST4.2x16	2
89	Soket head cap screw M5x55	4
90	Spring washer 5	4
91	Flat washer 5	4
92	+ Pan head tapping screw ST4.2x16	5
93	Handle cover	1
94	Switch	1
95	Capacitance 0.33µF	1
96	Handle	1
97	Flat washer 5	2
98	Spring washer 5	2
99	+ Pan head screw M5x22	2
100	Tapping screw ST5x25	1
101	Cable sheath	1
102	Supply cord H07RN-F2X0.75-2300	1
103	Cable pressing plate	1
104	+ Pan head tapping screw ST4.2x16	2
106	Depth gauge	1
107	Square head screw M8x50	1
108	Hoop	1
109	Bracket	1
110	Saddle	1
112	Assistant handle	1
120	Disc spring 14.3x35x2.6 (1.2)	3
121	Washer 14.2x24x3	1
122	Roundwire snap rings for shaft 12x1.5	1